DESCRIPTION

LED T8 Plug & Play replacement lamps are a convenient option to replace fluorescent T8 lamps at a fraction of the energy cost.

FEATURES

- · Frosted glass lens reduces visual glare
- Suitable for use in totally enclosed fixtures
- Instantaneous full light output upon power-up
- No rewiring or modifications of any kind required
- Solid state replacement for 2 ft. 15W and 17W T8 G13 base
- Delivers 156 Lumens per Watt for highly efficient performance
- Operates on most electronic T8 (instant & programmed rapid start) ballasts, select dimming ballasts, and AC emergency ballasts as listed in compatibility list. Visit pltsolutions.com to view complete ballast compatibility information.

LISTINGS

- UL damp location rated
- FCC Part 18
- RoHS
- DesignLights Consortium® 5.1 Standard meets the requirements for the highest DLC qualification for efficacy and lumen maintenance; DLC Part Number - PLTSP4D114

WARRANTY

• 5 year limited warranty; see pltsolutions.com for warranty details

APPLICATIONS

- Office Lighting
- High Bays
- Industrial Strips
- Warehouses
- Stairwells
- Cold Storage

project name	type
catalog number	
comments	voltage
approved by	date











	Power Consumption	8 Watt			
PERFORMANCE	Lumens	1250			
	Efficacy (LPW)	156			
	CRI	80+			
	Beam	210 Degree			
	сст	4000K			
	LED L70 Life Hours	≥100,000			
ELECTRICAL	Power Factor	0.9			
	THD	>20%			
	Input Voltage	120-277			
CONSTRUCTION	Operating Temperature	-4°F to 113°F (-20°C to 45°C)			
	Base	G13			
	Lens	Frosted			
LISTINGS	Certifications	UL Rated; FCC			
	Material Usage	RoHS - No mercury or lead			
	Environment	Suitable for use in enclosed fixtures - Damp Location Rated			

PERFORMANCE SUMMARY

Item #	Length	Lumens	Watts	LPW	ССТ	CRI	Beam	Envelope	LED L70 Life Hours	DLC Level	DLC #
PLT-90225	2'	1250	8	156	4000K	+08	210	Glass	≥100,000	5.1 Standard	PLTSP4D114

DIMENSIONS



WARNINGS

- Review all installation instructions and confirm use of a compatible ballast before installing PLT LED T8 tubes
- Does not operate on magnetic or T12 ballasts
- Use of an incompatible ballast, poor socket connection or other improper installation can result in reduced lamp lifetime, arcing or localized overheating