



Parts needed to mount the JAZ extrusion





Tools needed for mounting:

- drill

NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure.



2. Mount the LED strip (B) in the extrusion. 1. Drill a hole in the extrusion (A) to feed the power cable. cross-section top view **3.** Suspend the extrusion using the hangers (C) and a chosen suspension **5.** Connect power to the LED strips. Insert the cover (D) and the end caps (E). system. The hanger manual can be downloaded at klusdesign.com cross-section Ε top view D