











Dimmer Compatibility Guide

776678 LED7G40/27K/FIL/E26/2

						er Dimmer	
					Recommended	Maximum	
	Manufacturer	Product	Model Number	Overall Rating	Minimum	Tested*	Notes
		IllumaTech	IPI06	Best	1	6	Dims down to 12%
	Leviton	SureSlide	6633-P	Best	1	6	Dims down to 1%
		Vizia	VPI06-1LZ	Good	2	6	Dims down to 11%
	Lutron	Toggler	TG-600	Best	1	6	Dims down to 10%
Incandescent/Halogen (Triac/Phase		Diva	DV-600	Best	1	6	Dims down to 1%
Cut/Leading Edge Dimmers)		Skylark	S-600	Best	1	6	Dims down to 1%
		Maestro	MAW-600	Good	2	6	Dims down to 12%, minor flicker LE with 3-6
		Titan	CD703-PW	Good	1	6	Dims down to 12%, minor flicker HE with 1
	Legrand	Harmony	D703-PTC	Good	1	6	Dims down to 1%, minor flicker LE with 1
		Harmony	H703-PTC	Good	1	6	Dims down to 1%, minor flicker LE with 1
		I	Terran		1		I
	Leviton	IllumaTech	IPL06	Best		6	Dims down to 1%
	Leviton	Sureslide	6674	Best	1	6	Dims down to 10%,
		Decora	6672	Best	1	6	Dims down to 5%
		Skylark Countour	CTCL-153	Best	1	6	Dims down to 1%, minor flicker below 20%, adjust ing LE above 20% advoid flicker
		Diva	DVCL-153PL	Best	1	6	Dims down to 1%, minor flicker below 20%, adjust ing LE above 20% advoid flicker
CFL/LED	Lutron	Maestro	MACL-153MLH	Best	1	6	Dims down to 10%, minor flicker below 20%, adjusting LE above 20% advoid flicker
		Skylark	SCL-153P	Best	1	6	Dims down to 1%, minor flicker below 20%, adjust ing LE above 20% advoid flicker
		Toggler	TGCL-153PH	Best	1	6	Dims down to 3%, minor flicker below 20%, adjusting LE above 20% advoid flicker
		Radio RA	RA2RR-6CL-PD	Best	1	6	Dims down to 1%, minor flicker below 20%, adjust ing LE above 20% advoid flicker
	Legrand	Harmony	DCL4S3-PTC	Good	1	6	Dims down to 1%, minor flicker below 25%, adjust ing LE above 25% advoid flicker
		Harmony	HCL453PTC	Good	1	6	Dims down to 1%, minor flicker below 25%, adjust ing LE above 25% advoid flicker
		Adorne Paddle	ADPD453LM2	Good	1	6	Dims down to 27%,
	1 24	Vizia IllumaTech	VPE04 IPE04	Best Best	1	6	Dims down to 10% Dims down to 8%
	Leviton					6	
		Decora	6615-P CTELV-303P	Good	1	6	Dims down to 35%
Electronic Low Voltage	Lutron	Skylark Countour		Best	1	6	Dims down to 10%
Electronic Low Voltage		Diva	DVELV-300P	Best	1	6	Dims down to 10%
		Maestro	MAELV-600	Best	1	6	Dims down to 10%
		Skylark	SELVB-300P	Best	1	6	Dims down to 10%
		VIERTI	VTEL-600M-W	Best	1	6	Dims down to 25%
	Legrand	Scene Director	SCELV	Good	1	6	
		Vizia	VPM-06	Good	2	6	Dims down to 7%. flicker at LE with 2
	Leviton	Decora	6613-P	Rest	2	6	Dims down to 3%, Ticker at LE With 2
Magentic Low Voltage	Lutron	Maestro	MALV-600	Good	2	6	Dims down to 12% with 2-6
maganite con voltage	Lutron	Harmony	DLV703-PW	Best	1	6	Dims down to 12% with 2-6 Dims down to 3%
	Legrand	Titan	CDLV703-PW	Good	1	6	Dims down to 3%  Dims down to 1%, minor flicker at LE with 1
	Legranu	iitali	CDLV703-FW	9000			Dillis down to 1/6, millior nicker at LE with 1
	Leviton	Decora Digital (Bluetooth)	DDMX1-BLZ	Good	1	6	Dims down to 13%, minor flicker at LE with 2-6
Smart Dimmer	Leviton	Decora Smart Wi-Fi	DX6HD-1BZ	N/A	-	-	Dirid down to 13/4, million model at the with 2 o
	Insteon	SwitchLin Remote Control dimmer	DAVID IVE	N/A			
	Lutron	Caseta Wireless smart dimmer Wi-Fi	PD-6WCL	Good	1	6	Dims down to 6% minor flicker at LE with 1-6
	Legrand	Adorne touch Wi-Fi TRU Universal	ADTH700RMTUW1	N/A		-	Dirid down to DA, millor richer at EE War 2 U
	Legrand	Adorne Sof Tap Wi-Fi TRU Universal	ADTP700RMTUW1	N/A			
	GE	Z WAVE	ZW3005	Good	1	6	Dims down to 5%, minor flicker at LE with 1-6
	- GL	I a more		0000			
		Adorne SofTap	ADTP703TU	Good	1	6	Dims down to 15%, minor flicker at LE with 1-6
		Miro Decorator	DRD4-W	Not Compatible	1	6	Flash at LE with 1-6
	Legrand	Harmony	H703PTUTC	Good	1	6	Dims down to 15% minor flicker at LE with 1-6
Universal		Adorne Whisper	ADWR700MMTUW2	Good	1	6	Dims down to 15% minor flicker at LE with 1-6
		Adorne Touch	ADTH700MMTUM2	Good	1	6	Dims down to 15% minor flicker at LE with 1-6
	Cooper	Decorator	DAL06P-C2-K-L	Best	1	6	Dims down to 1%.

\*Maximum Tested (Lumpp per Dinmer) - Additional lumps, may work with your dimmer system. For maximum capacity please consult dimmer manufacturer.
(May openience" Topo on", light cannot be turned on immediately to their minimum level. The sider needs to be raised above the minimum light level for the lights to first turn on if they
were instally off. The acide can be between Eq. to a lover light level, the dimmer cannot be runned on to just the minimum level.

verall Rating						
Not Compatible	One or more of the following observed: Major flickering at various points, significant audible noise, no dimming range, does not turn off.					
Bad	One or more of the following observed: Some flickering observed at various points, audible noise may be present, dimming not smooth.					
9000	One or more of the following observed: Minor Rickering at some point may exist. Dead travel may exist, which means there may be periods of time when the slider (or other form of control button) is moved without affecting the light level. These periods of dead travel are minor and most of the time not visible.					
Best	Most of the following observed: No flickering, minimal audible noise (typically less than 25 dBa), wide dimming range - can dim down to 20% or less of light output.					
High End (H.E.) Dead Travel	Determines how much, if any, dead travel exists at the too and bottom of the dimmer's range. Dead travel is when the slider can be moved without affecting the light level.					
Law End (LE) Dood Travel	stermines now made, it stry, were there expend to the comment of the dimines a straight. Seed there is when the street can be more white the control of the difference of the control of t					